



Continental IO-550 Series

Covered Components

Case
 Camshaft
 Crankshaft
 Crankshaft Main Bearings
 Crankshaft-Std or Roller
 Cylinder Assembly
 Piston
 Piston Pin
 Rings Top Compression
 Rings Oil Regulator
 Connecting Rod Assembly
 Connecting Rod Bearings
 Intake Valve

Covered Components

Exhaust Valve
 Valve Spring Inner
 Valve Spring Outer
 Rocker Arm Shaft
 Rocker Arm Exhaust
 Rocker Arm Intake
 Gasket Kit
 Oil Pump Impeller Driving
 Oil Pump Impeller Driven
 Oil Pump Housing
 Hydraulic Tappet Body
 Hydraulic Tappet Socket
 Hydraulic Tappet Plunger

Covered Accessories

Alternator
 Starter / Adapter
 Magneto
 Engine Driven Fuel Pump
 Propeller Governor

Scheduled Services

Annual Engine Inspection	
Engine / Continental IO-550	Rebuilt
Engine and Accessory Inspections	
Propeller / Governor / Hub	
Accessories	
Oil Changes / Filter / S.O.A.P. Tests	

* Any cylinder head found to be cracked between the fuel injector port and the spark plug port are not covered.



Continental TSIO-550 Series

Covered Components

Case
Camshaft
Crankshaft
Crankshaft Main Bearings
Crankshaft-Std or Roller
Cylinder Assembly
Piston
Piston Pin
Rings Top Compression
Rings Oil Regulator
Connecting Rod Assembly
Connecting Rod Bearings
Intake Valve

Covered Components

Exhaust Valve
Valve Spring Inner
Valve Spring Outer
Rocker Arm Shaft
Rocker Arm Exhaust
Rocker Arm Intake
Gasket Kit
Oil Pump Impeller Driving
Oil Pump Impeller Driven
Oil Pump Housing
Hydraulic Tappet Body
Hydraulic Tappet Socket
Hydraulic Tappet Plunger

Covered Accessories

Alternator (Overhauled)	Turbocharger
Starter (Overhauled)	Intercooler
Magneto (Overhauled)	Bracket Turbo Support L/R
Engine Driven Fuel Pump (Overhauled)	Controller Assembly
Propeller Governor (Overhauled)	Valve Assembly

Scheduled Services

Annual Engine Inspection	
Engine / Continental TSIO-550	Rebuilt
Engine and Accessory Inspections	
Propeller / Governor / Hub	
Accessories	
Oil Changes / Filter / S.O.A.P. Tests	

* Any cylinder head found to be cracked between the fuel injector port and the spark plug port are not covered.